National Transportation Safety Board NTSB ID: NYC00WA038 Most Critical Injury: Fatal PRELIMINARY REPORT Occurrence Date: 11/26/1999 Investigated By: Unknown AVIATION ICAO Report Submitted: Occurrence Type: Accident ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone 0526 **NAIROBI** Aircraft Information Registration Number Aircraft Manufacturer Model/Series Number 208 5YRAN Cessna Type of Aircraft: Airplane Homebuilt Aircraft? No Fatal Serious Minor None 4 0 Injury Summary:

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 26, 1999, at 0526 local time, the pilot and three passengers onboard a Cessna 208, Kenyan registry 5Y-RAN were fatally injured, as the airplane departed Jomo Kenyatta Airport (HKNA), Nairobi, Kenya. The damage to the airplane is unknown. The flight was en route to Dar es Salaam (HTDA), Tanzania.

Air Medical Transport Flight: No

According to press reports, the airplane belonged to Kenyan Charter Company Aircraft Leasing Services, and was ferrying cargo to Dar es Salaam, Tanzania. The airplane occupants were Kenyans and worked for the company. In addition, the press reported a "heavy mist" was present at the time of takeoff.

The Safety Board has assigned an accredited representative. However, no travel is planned. A technical representative from Cessna Aircraft Company will travel to the site.

The investigation is being conducted under the control of the Kenyan Government, and any further information, may be obtained from:

The Chief Inspector of Accidents Directorate of Civil Aviation P.O. Box 30163 Nairobi, Kenya

TRANSO_
National Transportation Safety Board
0 7
PRELIMINARY REPORT
2 3 €
AYIATIQN

NTSB ID: NYC00WA038

PRELIMINARY REPORT AVIATION			Occurrence Date: 11/26/1999]					
			Occurrence Type: Accident									
Other Aircraft Ir												
Registration Number								Model/Sei	Model/Series Number			
Accident Inform	ation							•				
Aircraft Damage:	Occurred Duri	ing:										
Property Damage:	Airport Facil	ity										
Crew	Name					Certificate No.				Injury		
Pilot												
2												
3												
4												
5												
6												
Operator Inform	nation											
Name Operator D KYNYAN CHARTER CO, A/C LEASING					or Desig	Pesignator Code Doing Business As						
Street Address Ci					City	,				State	Zip Code	
-Type of Certificate(s) Held: None												
Air Carrier Operating Certificate(s):												
Operating Certificate:						Operator Certificate:						
Regulation Flight (Conducted Und	ler: Non-U.S., Non	-Comm	ercial								
Type of Flight Oper	rations Conduc	ted: Other Work Us	se									
Flight Plan/Itine	erary											
Type of Flight Pla	n Filed: Unkno	own										
Last Departure F	Point					State	Airport Identifier					
NAIROBI, KENYA						OF	HKN	4				
Destination						State	Airport	Identifier				
DAR ES SALAAM						OF	HTDA	A				
Weather Inform	ation											
Investigator's Source:					Faci	lity ID:	Observation	n Time	(Local): 0000			
Sky/Lowest Cloud Condition: Unknown						0 Ft. AGL						
Lowest Ceiling: Ur	nknown		0	Ft. AGL	V	isibility:	0	SM	Altim	neter:		"Hg
		PRELIMINARY	INFOR	MATIO	N - SUI	ВЈЕСТ ТО	CHANC	GE				Page 2

TRANSPO

NTSB ID: NYC00WA038

National Transportation Safety Board PRELIMINARY REPORT AVIATION			NYCUUWAU38							
			Occ	currence D	Pate: 11/26/1999					
			Occ	urrence T	ype: Accident					
Weather Information		(Continued from page 2)								
Temperature:	°C	Dew Point:	°C							
Wind Speed:	Kts.	. Gusts: K	ίts.	Weath	eather Conditions at Accident Site:					
Administration Data										
Notification From						Date 11/26/1999	Local Time 0000			
FAA District Office/Coordinator					Investigator-In-Charge (IIC) ROBERT L. HANCOCK					